

Laboratory measurement of airborne sound insulation of small building elements Element-normalized level difference according to BS EN 20140-10:1992 BRE horizontal transmission suite (B9 051-053)

Client: Ryt

Rytons Building Products Ltd

Test date: 23/07/2007

Test number: L107-155

Test element: Ventilator

0578

Filler wall area:

9.8 m²

Description:

TALH&M ventilator assembly:

x1 MFAB96, TAL8000 AirLiner, HM85F Internal (OPEN)

Source room volume:

130 m³

Air temperature:

19 °C

Receive room volume:

115 m³

Air relative humidity:

74 %

Frequency	Reverberation	Background	Source	Receive	D _{n,e}	٦
	time	level	level	level		
(Hz)	(s)	(dB)	(dB)	(dB)	(dB)	
50	3.14	26.4	92.3	59.4	36.6	
63	2.21	20.6	100.1	68.1	34.1	c
80	1.83	15.3	99.7	64.6	36.4	c
100	1.67	13.4	100.5	61.3	40.1	c
125	2.03	12.2	103.1	67.0	37.1	2
160	1.87	19.4	102.2	64.6	37.6	-
200	1.87	34.8	102.2	63.4	38.9	
250	1.72	13.7	100.1	65.4	34.4	
315	1.68	12.8	100.2	69.4	30.3	١
400	1.61	23.9	99.7	68.3	30.8	
500	1.66	9.9	99.0	66.8	31.7	
630	1.60	10.3	98.6	60.4	37.6	
800	1.47	9.8	97.7	57.4	39.3	
1,000	1.45	15.6	96.5	56.0	39.5	
1,250	1.51	12.4	98.3	54.0	43.4	
1,600	1.48	6.2	98.9	54.9	43.1	
2,000	1.52	6.4	97.5	49.1	47.6	
2,500	1.50	7.0	97.8	44.8	52.1	
3,150	1.45	7.6	97.8	42.6	54.2	
4,000	1.38	8.0	98.5	43.8	53.4	
5,000	1.26	9.8	95.6	39.8	54.2	

x Adjusted for flanking transmission

o Correction = 1.3 dB

0 00170011011 110 025						
Rating according to BS EN ISO 717-1	:1997					
$D_{\text{n,e,w}}(C;C_{\text{tr}}) = 39 (0;-2) dB$	C ₅₀₋₃₁₅₀	= 0 dB	C 50-5000	= 1 dB	C ₁₀₀₋₅₀₀₀	= 1 dB
	C _{tr,50-3150}	= -2 dB	$C_{\rm tr,50-5000}$	= -2 dB	$C_{ m tr,100-5000}$	= -2 dB
Evaluation based on laboratory measurement resu	Its obtained by an engin	neering method				

Based on the data provided in BS EN 20140-2:1993 it is estimated that the measurement uncertainty should not exceed ± 1 dB for the single-number quantity ($D_{n,e,w}$) and should not exceed the values in Table A1 of BS EN 20140-2:1993 for the data in the individual third octaves ($D_{n,e,w}$)

Laboratory airborne sound insulation testing of Rytons Building Products Ltd ventilator systems



Laboratory measurement of airborne sound insulation of small building elements Element-normalized level difference according to BS EN 20140-10:1992 BRE horizontal transmission suite (B9 051-053)

Client:

Rytons Building Products Ltd

Test date: 23/07/2007

Test number: L107-155

Test element: Ventilator

Filler wall area:

9.8 m²

Description:

TALH&M ventilator assembly;

x1 MFAB96, TAL8000 AirLiner, HM85F Internal (OPEN)

Source room volume:

130 m³

Air temperature:

19 °C


Receive room volume:


115 m³

Air relative humidity:

74 %

	$oldsymbol{D}_{n,e}$	l
Frequency	One-third	
(Hz)	octave	
	(dB)	
50	36.6	o
63	34.1	٥
80	36.4	0
100	40.1	o
125	37.1	x
160	37.6	
200	38.9	





x Adjusted for flanking transmission

o Correction = 1.3 dB

Third octave band centre frequency (Hz)

Rating according to BS EN ISO 717-1:1997

 $D_{n,e,w}(C;C_{tr}) = 39 (0;-2) dB$

 $C_{50-3150}$ $C_{\rm tr,50-3150}$ = 0 dB= -2 dB C 50-5000 $C_{\text{tr,50-5000}}$ = 1 dB= -2 dB C₁₀₀₋₅₀₀₀ $C_{\rm tr,100-5000}$ = 1 dB= -2 dB

Evaluation based on laboratory measurement results obtained by an engineering method

Based on the data provided in BS EN 20140-2:1993 it is estimated that the measurement uncertainty should not exceed ±1 dB for the single-number quantity (D_{n,e,w}) and should not exceed the values in Table A1 of BS EN 20140-2:1993 for the data in the individual third octaves (D_{n,e,w})



Laboratory measurement of airborne sound insulation of small building elements Element-normalized level difference according to BS EN 20140-10:1992 BRE horizontal transmission suite (B9 051-053)

Client:

Rytons Building Products Ltd

Test date: 23/07/2007

7/2007 **Test number**: L107-156

Test element: Ventilator

0578

Filler wall area:

9.8 m²

Description:

TALH&M ventilator assembly;

x1 MFAB96, TAL8000 AirLiner, HM85F Internal (CLOSED)

Source room volume:

130 m³

Air temperature:

19 °C

Receive room volume:

115 m³

Air relative humidity:

74 %

Frequency	Reverberation	Background	Source	Receive	D _{n,e}	٦
	time	level	level	level		
(Hz)	(s)	(dB)	(dB)	(dB)	(dB)	
50	3.14	22.3	91.7	58.9	36.4	- 0
63	2.21	15.5	100.0	67.8	34.3	0
80	1.83	13.3	99.7	63.5	37.4	0
100	1.67	13.7	100.1	60.7	40.3	0
125	2.03	10.7	103.0	66.8	37.3	x
160	1.87	20.1	102.3	64.4	38.0	
200	1.87	35.3	102.4	63.3	39.2	
250	1.72	13.7	100.0	65.2	34.6	
315	1.68	12.6	100.1	69.1	30.5	
400	1.61	22.1	99.7	68.1	31.0	
500	1.66	9.3	99.0	66.4	32.1	
630	1.60	9.3	98.6	59.8	38.2	
800	1.47	10.5	97.6	56.9	39.7	
1,000	1.45	16.1	96.4	55.7	39.6	
1,250	1.51	11.6	98.2	54.2	43.1	
1,600	1.48	5.8	98.9	54.9	43.1	
2,000	1.52	6.1	97.4	48.8	47.8	
2,500	1.50	6.7	97.8	43.7	53.2	
3,150	1.45	7.8	97.9	41.4	55.5	
4,000	1.38	8.4	98.6	40.9	56.5	
5,000	1.26	8.7	95.7	36.3	57.8	

x Adjusted for flanking transmission

o Correction = 1.3 dB

Rating according to BS EN ISO 717-1:	1997					******
$D_{\text{n,e,w}}(C;C_{\text{tr}}) = 40 \text{ (-1;-3) dB}$	$C_{50-3150} \ C_{ m tr,50-3150}$	= -1 dB = -3 dB	$C_{50-5000}$ $C_{\text{tr,50-5000}}$	= 0 dB = -3 dB	$C_{100-5000} \ C_{tr,100-5000}$	= 0 dB = -3 dB
Evaluation based on laboratory measurement result	ts obtained by an engin	neering method				

Based on the data provided in BS EN 20140-2:1993 it is estimated that the measurement uncertainty should not exceed ± 1 dB for the single-number quantity ($D_{n,e,w}$) and should not exceed the values in Table A1 of BS EN 20140-2:1993 for the data in the individual third octaves ($D_{n,e,w}$)

Laboratory airborne sound insulation testing of Rytons Building Products Ltd ventilator systems



Laboratory measurement of airborne sound insulation of small building elements Element-normalized level difference according to BS EN 20140-10:1992

BRE horizontal transmission suite (B9 051-053)

Rytons Building Products Ltd

Test date: 23/07/2007

Test number: L107-156

Test element: Ventilator

0578

Filler wall area:

9.8 m²

Description:

TALH&M ventilator assembly:

x1 MFAB96, TAL8000 AirLiner, HM85F Internal (CLOSED)

Source room volume:

130 m³

Air temperature:

19 °C


Receive room volume:

Air relative humidity:

115 m³

74 %

	D _{n,e}	ı
Frequency	One-third	I
(Hz)	octave	ı
	(dB)	l
50	36.4	I
63	34.3	l
80	37.4	١
100	40.3	1
125	37.3	I
160	38.0	l
200	39.2	Į
250	34.6	l
315	30.5	l
400	31.0	1
500	32.1	I
630	38.2	1
800	39.7	1
1,000	39.6	
1,250	43.1	
1,600	43.1	1
2,000	47.8	
2,500	53.2	
3,150	55.5	1
4,000	56.5	1
5,000	57.8	



x Adjusted for flanking transmission

o Correction = 1.3 dB

Third octave band centre frequency (Hz)

Rating according to BS EN ISO 717-1:1997

 $D_{n,e,w}(C;C_{tr}) = 40 (-1;-3) dB$

 $C_{50-3150}$ $C_{tr,50-3150}$ = -1 dB= -3 dB C₅₀₋₅₀₀₀ $C_{\text{tr,50-5000}}$ = 0 dB= -3 dB C₁₀₀₋₅₀₀₀ C_{tr,100-5000} = 0 dB= -3 dB

Evaluation based on laboratory measurement results obtained by an engineering method

Based on the data provided in BS EN 20140-2:1993 it is estimated that the measurement uncertainty should not exceed ±1 dB for the single-number quantity (D_{n,e,w}) and should not exceed the values in Table A1 of BS EN 20140-2:1993 for the data in the individual third octaves (D_{n,e,w})

